

$S_p = 6,2 \text{ mA/V}$
 $R_i = 600 \text{ k}$
 $P_a = \text{max. } 2 \text{ W}$

$S_T = 2 \text{ mA/V}$
 $R_i = 50 \text{ k}$
 $\mu = 100$
 $P_a = \text{max. } 1 \text{ W}$

