

A
 $S=1,6\text{mA/V}$
 $\mu=68$
 $R_i=40\text{k}$
 $P_a=\text{max. } 1,5\text{W}$

B
 $S=7,2\text{mA/V}$
 $\mu=5,4$
 $R_i=750\Omega$
 $P_a=\text{max. } 10\text{W}$

