

$S_p = 4,4 \text{ mA/V}$
 $R_i = 100 \text{ k}$
 $P_a = \text{max. } 2 \text{ W}$

$S_T = 4 \text{ mA/V}$
 $R_i = 17,5 \text{ k}$
 $\mu = 70$
 $P_a = \text{max. } 1 \text{ W}$

