

A
 $S=1,6 \text{ mA/V}$
 $\mu=68$
 $R_i=40 \text{ k}$
 $P_a=\text{max. } 1 \text{ W}$

B
 $S=6,5 \text{ mA/V}$
 $\mu=6$
 $R_i=925 \Omega$
 $P_a=\text{max. } 7 \text{ W}$

