

A  
 $S = 1,6 \text{ mA/V}$   
 $\mu = 64$   
 $R_i = 40 \text{ k}$   
 $P_a = \text{max. } 1,5 \text{ W}$

B  
 $S = 7,2 \text{ mA/V}$   
 $\mu = 5,4$   
 $R_i = 750 \Omega$   
 $P_a = \text{max. } 11 \text{ W}$

