

$S_p = 6,5 \text{ mA/V}$   
 $R_i = 200 \text{ k}$   
 $P_a = \text{max. } 2,3 \text{ W}$

$S_T = 8 \text{ mA/V}$   
 $R_i = 5 \text{ k}$   
 $\mu = 40$   
 $P_a = \text{max. } 2 \text{ W}$

