

$S_p = 6,2 \text{ mA/V}$
 $R_i = 300 \text{ k}$
 $P_a = \text{max. } 2 \text{ W}$

$S_T = 3,3 \text{ mA/V}$
 $R_i = 5,75$
 $\mu = 19$
 $P_a = \text{max. } 2,6 \text{ W}$

