

$S_p = 7 \text{ mA/V}$
 $R_i = 400 \text{ k}$
 $P_a = \text{max. } 3 \text{ W}$

$S_T = 2,1 \text{ mA/V}$
 $R_i = 8,1 \text{ k}$
 $\mu = 17$
 $P_a = \text{max. } 2,4 \text{ W}$

