

$S = 11 \text{ mA/V}$   
 $V_{g1} = -8 \text{ V}$   
 $\mu_{g2g1} = 15$   
 $R_i =$   
 $P_a = \text{max. } 50 \text{ W}$

